

La Boschiny, Inc. 1889 Petaluma Dr. Chula Vista, CA 91913 USA

www.caleasytouch.com



Product of Orbit Technology Corporation

CAL 2D Getting Started Features and Manual

Table of contents

1	Gettir	ng the information	3
2	Featu	res	4
3	Instal	software CAL Getting Started	5~8
4	Bend	Table operation manual	
	4.1	How to make a sample	9
	4. 2	How to back up and restore the bend table data	10
5	CAL b	ending software operation manual	
	5. 1.	How to use CAL	11
	5. 2.	How to change tools	12
	5. 3.	How to lock the important sizes	13
	5. 4.	How to reverse tool and back-gauge direction	14
	5. 5.	How to import a custom die	15
	5. 6.	How to import a custom punch	16
	5. 7.	How to select tools manually	17
	5. 8.	How to verify collision manually	18
	5. 9.	How to create multiple profiles	19
	5.10.	How to use calculator D and L value	20
	5.11.	How to use angle correction	21
	5.12.	How to use multiple punches	22
	5.13.	How to add bend in program	23
	5.14.	How to use back-gauge compensation	24
	5.15.	How to enter insertion/hardware	25
6	Conta	ct information	26

1. Getting the information

The CAL bending software meets a touch-enabled high-performance computer.

This allows you to operate CAL bending software on site with touch screen computer (tablet PC) such as HP touchsmart series and Dell Inspiron duo.

We encourage you to use a touch screen computer to maximize the EASY TOUCH function of this great bending software.

System requirements

1.66GHz or faster preferable (minimum 1GHz)2GB memory preferable (minimum 1GB)1024 x 600 or higher resolutionMicrosoft Windows XP or later Windows

2. Features

This bending software CAL has the following features:

- Automatic bending sequence
- Automatic tool selection
- Automatic bending program for machine depth value and backgauge position (Length)
- Automatic collision check
- Lock-in important bend length
- Insert/hardware and embossing check
- Bending simulation
- Able to load custom tools
- The best tooling library
- Captures all factors of bending with one sample
- Automatic predictions of angle and back-gauge position
- Automatic bend deduction, K-Factor, bend allowance and inner radius finder (It calculates from one sample in Bend Table.)
- Able to create own bend table
- Able to import your bend table saved CSV format from Excel file.

- 3. Installing bending software "CAL"
- 1) Connect Dongle
- 2) Insert CD ROM or UBS to install software

Important information: Before starting

Before starting CAL/Press Brake operator, follow the setting that suit its operation.

- i. Unit (Inch/Metric), Machine name and Ram stroke axis type
- ii. Punch and die

Step 1: Unit, Name and Ram

Please select Unit (inch/metric) name and ram stroke axis type as follows:

MANAGER> OPETIONS> GENERAL for Unit

MANAGER> OPTIONS> MACHINE for name and ram

Please refer to manual page 7.

Step 2: Punch and Die

You need to add all punches and dies in the software before you use this bending software.

All punches and dies are gray color that means there are no tools added into the software. This bending software CAL will use only punch and die that you selected from tooling library. Here is how to setup the punches and dies for your operation.

Please refer to page 8.

- 1. Click CAL short-cut to open CAL
- 2. Click MANAGER tab located top left
- 3. Pull down menu and select TOOLS
- 4. Click Punches tab (it may open)

- 5. Click punch or punches from left side of library.
- 6. Click ADD button located in right side.

We have the most punches number from main suppliers.

Please do the same procedure for the dies.

- 1. Click Dies tab
- 2. Click die or dies from left side of library.
- 3. Click ADD button located in right side.

If you have custom tools then click custom punches or custom dies tab to load from your computer.

Refer to manual page 15 and 16.

Now you can use Bending Software and Bend Table.

HOW TO SELECT MACHINE NAME AND RAM STROKE AXIS TYPE BEFORE STARTED

CAL CAL for RG50[Europ	pean]		the barrant			
MANAGER -	SKETCH SIZE INSE	RTION ADJUST		GRAM SIMULATE	ок	
Profiles	 Thickness 		neral Colors Maci Machine Name Ram Stroke Axis Type Stroke down Decimal Place Back Gauge	Inine BG Comp About Your machine name Amada D axis AccurPress Y axis Amada D axis FMB MS axis Toyo/Mitsubishi axis Other Increment • OK		
3	🥭 🚺 😔 🛛	AL 🔯				EN 🔺 🏴 间 🚺 11:17 AM 11/25/2011

You can name your software with your machine name that is designated to use this software. Click MANAGER

Select OPTIONS from pull-down menu

Select General for unit, Machine for name and Ram stroke axis type

General:

You can select English (inch) or Metric (millimeter) Machine:

Just type name in the Machine Name box

Select Axis type from pull-down menu

HOW TO USE TOOLING LIBRARY

CAL tooling library (How to use)

http://www.youtube.com/watch?v=XRnbgNAkjPU

NEW	Tools	_	01630 (User)	_	_ - X
			e Holders Custom Punches Preference Inventory		
IMPORT	All00402	All00408	All - All - 00415		Preference
SAVE	[00402] [60402] [64802] [14802]	[00408] [60408] [64808]	[00415] [00415] [60415] [64815] [14815]		REMOVE
TOOLS	00423 [00423] [60423] [64823 [4823]	[60430]	00448 [00448] [60448] [64848] [14848]		
BEND TABLE	00480 [00480] [00482] [64822] [4882]	00490 [00490] [60492] [64892]	00800 [00800] [60800] [64902]		
	01002 [01002]	01602 [01602]	[04902] 01608 [01608] [61608] [64708] [4708] [14708]	SELECT PUNCH TO VIEW INFORMATION	X Close
(2)	2			رحالي ا	

This Cal video will show you how to organize the tooling inventory for faster search results.

Clk manager----then tools.

Cal lets you create search parameters for your tool searches by using

CATALOG TYPE PREFERENCES INVENTORY

To remove a tool from your list, highlight the toolThe right side of the screen will show the tooling info so you can verify that it is the one you want. ... Click the remove button on the right side of the screen.

HOW TO MAKE SAMPLE DATA WITH BEND TABLE

Bend table sample data operation

http://www.youtube.com/watch?v=5OM3fjafts0&feature=related

	Sho	n Set		Edit	Add					V Widt	h						
Angle 90.0 🔿		ickness		0.236		0.315	0.394	0.472		0.63	0.709	0.787	0.984	1.26	1.575	1.969	2.48
K-factor	Gauge 20	0.036	4mm	6	7	8	10	12	14	16	18	20	25	32	40	50	63
Y-factor	18	0.048															
Bend Allowance	16	0.06															
Inside Radius	14 13	0.075															
	12	0.105														-	
Outside BD	11	0.12															
Inside BD	10	0.135															
Tangent BD	9 7	0.150															
Commits Data	1/4"	0.25															
Sample Data Punch	5/16"	0.312															
Die	3/8" 7/16"	0.375															
Angle	1/2"	0.5		-					-								
Aligie	5/8"	0.625															
	3/4"	0.75															
	7/8"	0.875															
	1.25"	1.25															
	De	fault	Trial B	end	Recomm	nended	Out	of Order									

This Cal video shows how to input new material sample data into the Bend Table.

You will enter the information from your bend sample.

Remember it does not need to be a specific angle, but approximately 100° is recommended.

Click "add new Material" from the top left corner.

Enter the material name & a description for future clarification---

When you are done clk add

Go to the top of your screen; click the "add" icon button for the bend data form

HOW TO BACK UP AND RESTORE THE BEND TABLE DATA

Bend table how to save the data

Gauge 4mm 6 7 8 10 12 14 16 18 20 25 32 40 50 63 Yfactor 18 0.048 -	Kator Kator Kator Mam 6 7 8 10 12 14 16 18 20 25 32 40 50 63 Krator Kator Raterial Supervision Material Supervision Supervis	Gauge mm 6 7 8 10 12 14 16 18 20 25 32 40 50 63 Vactor 18 0.048 1 14 16 18 20 25 32 40 50 63 Bend Allowance 16 0.06 1											V Wid	lth						
Kfactor 20 0.036 0 Yfactor 18 0.048 0 0 Bend Allowance 16 0.06 0 0 Inside Radius 13 0.09 0 0 0 Outside BD 10 0.12 0 0 0 0 Inside Radius 12 0.105 0 0 0 0 0 Sample Data 7 0.179 0	K-factor 20 0.036 Image: Constraint of the second seco	Kfactor 20 0.038 Image: Constraint of the second sec	igle 90.0 📑		ickness															
Y factor 18 0.048 0.048 Bend Allowance 16 0.06 0.06 Inside BD 12 0.105 0.01 Inside BD 10 0.12 0.155 Inside BD 10 0.135 0 I angent BD 9 0.150 0.166 I angent BD 7 0.179 0.166 I angent BD 7 0.179 0.166 I angent BD 9 0.150 0.01 I angent BD 7 0.179 0.166 I angent BD 7 0.179 0.166 I angent BD 9 0.150 0.016 I angent BD 9 0.150 0.016 I angent BD 7 0.179 0.166 I angent BD 7 0.179 0.16 J angent BD 0.160 0.12 0.16 J angent BD 0.160 0.12 0.16 J angent BD 0.176 0.16 0.16 J angent BD 0.176 0.16 0.16 J angent BD	Vr.tactor 18 0.048 Image <	Y factor 18 0.048 Image: Constraint of the second o	K-factor		0.036	4mm	6	7	8	10	12	14	16	18	20	25	32	40	50	63
Bend Allowance 14 0.075 Inside Radius 13 0.09 12 0.105 13 0.09 14 0.075 15 0.09 16 0.09 17 0.135 18 0.09 19 0.150 10 0.135 Tangent BD 9 9 0.160 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.25 114" 0.56 114" 0.575 114" 1.25" 1125" 1.25	Inside Radius 14 0.075 Image Restore Inside Radius 13 0.09 Image Restore Dutside BD 12 0.105 Image Restore 11 0.12 Image Restore Image Restore 10 0.135 Image Restore Image Restore 114" 0.26 Image Restore Image Restore 114" 0.65 Image Restore Image Restore 114" 0.625 Image Restore Image Restore 112" Image Restore </td <td>Bend Allowance 14 0.075 Image and allowance Setup Inside BD 12 0.09 Image and allowance Image and allowance</td> <td>Y-factor</td> <td>18</td> <td>0.048</td> <td></td>	Bend Allowance 14 0.075 Image and allowance Setup Inside BD 12 0.09 Image and allowance	Y-factor	18	0.048															
Inside Radius 13 0.09 Image: Stap Outside BD 12 0.105 Image: Stap Inside BD 10 0.135 Image: Stap 10 0.135 Image: Stap Image: Stap 9 0.160 Image: Stap Image: Stap 9 0.160 Image: Stap Image: Stap 9 0.150 Image: Stap Image: Stap 10 0.135 Image: Stap Image: Stap 10 0.135 Image: Stap Image: Stap 10 0.160 Image: Stap Image: Stap 11 0.25 Image: Stap Image: Stap 112 0.5 Image: Stap Image: Stap 112 1.25 Image: Stap Image: Stap 125 Image: Stap Image: Stap Image: Stap 12	Inside Radius 13 0.09 Image Radius Image Radius <td>Inside Radius 13 0.09 Image: 12 0.106 12 0.106 Image: 12 Image: 12</td> <td>Bend Allowance</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Inside Radius 13 0.09 Image: 12 0.106 12 0.106 Image: 12	Bend Allowance										1							
Outside BD 12 0.105 Image: Construction of the system	Dutside BD 12 0.105 Material Type Width Thickness Attribute System About Inside BD 10 0.135	Outside BD 12 0.106 Material Type V Width Thickness Attribute System About Inside BD 10 0.135											Se Se	tup		-	-		-	-
Inside BD 10 0.12 Image is a statute Image is a	Inside BD 11 0.12 Image and type ▼ Minutes Finitude Provide the second	Inside BD 10 0.12 10 0.135																	0]
Tangent BD 9 0.160 Machine Name RG50 sample Data 7 0.179 Image: Constraint of the same state of the same	Tangent BD 9 0.160 Image: Constraint of the second s	Tangent BD 9 0.150 All											M	aterial Typ	e V Wid	th Thic	kness A	Attribute	System	About
Jampie Data Punch 7 0.179 Die 316" 0.312	International constraints In	iample Data 7 0.179 Image: Constraint of the state of the s												Machine	e Name		RG50			
Sample Data 6/16" 0.312 Image Metric (Millimeters) Jia 0.375 Image Image </td <td>ample Data Punch 6/16" 0.312 Metric (Millimeters) Die 1/16" 0.438 Imple Data <td< td=""><td>Sample Data Punch 5/16" 0.312 0.375 Metric (Millimeters) Die 1/16" 0.438 Image: Comparison of the state of the state</td><td>Tangent BD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>_</td><td></td><td></td><td></td><td></td></td<></td>	ample Data Punch 6/16" 0.312 Metric (Millimeters) Die 1/16" 0.438 Imple Data Imple Data <td< td=""><td>Sample Data Punch 5/16" 0.312 0.375 Metric (Millimeters) Die 1/16" 0.438 Image: Comparison of the state of the state</td><td>Tangent BD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>_</td><td></td><td></td><td></td><td></td></td<>	Sample Data Punch 5/16" 0.312 0.375 Metric (Millimeters) Die 1/16" 0.438 Image: Comparison of the state	Tangent BD													_				
Punch 3/8" 0.375 metric (minimetris) Die 7/16" 0.438 Image: Comparison of the state of the	Punch 3/8" 0.375 metric (minimetrix) Die 7/16" 0.438 Image: Comparison of the compari	Punch 3/8" 0.375 Image: Constraint of the second secon	Sample Data									-				-				
Angle 1/2" 0.5 Angle 1/2" 0.5 Angle Ram Stroke Angle 3/4" 0.75 Angle Punch Style Solid-Standard 7/8" 0.875 Angle Die Style Solid-Standard 1 1 Die Style Solid - Data Base Maintenance Image: Restore Image: Restore Image: Restore	Angle 1/2" 0.6 Image: Constraint of the second seco	Angle 1/2" 0.5 Angle Ram Stroke Amada D axis Amada D axis <td>Punch</td> <td></td> <td>0</td> <td>Metric (</td> <td>Millimete</td> <td>ers)</td> <td></td> <td></td>	Punch												0	Metric (Millimete	ers)		
Arigie 5/6" 0.625 Ram Stroke Amada D axis 3/4" 0.75 Dia Stroke Punch Style Solid-Standard 1" 1 Dia Style Solid Dia Style 125" 1.25" Dia Style Dia Base Maintenance	Angre 66° 0.625 Amada D axis 3/4" 0.76 Diamondary 7/8" 0.875 Diamondary 1" 1 Diamondary 1.25" 1.25 Diamondary	Angle 5/8" 0.625 Amada D axis 3/4" 0.75 Diamondary Punch Style Solid-Standard 1" 1 Diamondary Diamondary 125" 1.25 Diamondary Diamondary	Die												6	Use Ke	yPad			
3/4" 0.75 7/8" 0.875 1" 1 1.25" 1.25	3/4" 0.75 7/8" 0.875 1" 1 1.25" 1.25 Die Style Solid Data Base Maintenance Image: Solid Soli	3/4" 0.75 7/8" 0.875 1" 1 1.25" 1.25 Die Style Solid Data Base Maintenance Image: Solid Image: Solid	Angle										-		-					
1" 1 1.25" 1.25 Die Style Solid Data Base Maintenance Solid	1" 1 1.25" 1.25 Die Style Solid • Die Style Solid • Data Base Maintenance With the second secon	1 1 1.25" 1.25 Die Style Solid • Data Base Maintenance Image: Construction of the style state of the style style state of the style style state of the style state of the style s												Ram	Stroke	Amada D	axis		Ŧ	
1.25" 1.25 Delete E Restore	1.25" 1.25 Delety solid - Data Base Maintenance Solid -	1.25" 1.25 Data Base Maintenance Image: Constraint of the style solid Data Base Maintenance Image: Constraint of the style solid												Punch	h Style	Solid-Sta	ndard		•	
Data Base Maintenance	Data Base Maintenance	Data Base Maintenance											-	Die	e Style	Solid				
				1.20	1.20									Data Ba	se Maint	enance				
× Close	X Close	Close												8	Delete		Back	up	R	estore
																	X Clo	se		

http://www.youtube.com/watch?v=0r7nZk7u2bg&feature=related

This Cal video will show you how to both back-up and restore your bend table files

1st Click your Set-up icon at the top of your page

Click the System tab and the back-up button

Now select the folder you created for your Bend Table Back-up

& click OK

A detail pop-up screen appears confirming completion. Click the OK button to close.

We recommend checking your Bend Table back up folder to verify that your data was saved.

You should have 1 folder and 3 files:

Tooling folder and the Bend samples, Bend Table database, machine files

To restore files

Click the set-up icon, Systems tab and the Restore button.

Select your Bend Table folder & click OK.


The detail screen appears confirming restoration

Click OK for your screen to automatically close.

HOW TO USE CAL

CAL basic operation 1

http://www.youtube.com/watch?v=gQj602CPCx0



Welcome to the overview of how to use CAL

To choose your measurement preference


Click manger icon and then English or metric measurement

-Then go to the Machine tab.

HOW TO CHANGE TOOLING

CAL tool change

http://www.youtube.com/watch?v=5_bKYJNIK5Q



This CAL video will show you how to manually change the tooling.

Click the punch to show the punch list. These are grouped by shape and tip radius.


-select the specific bracketed # of the tool for proper information. You can scroll in to view the changes.

-Click the die for the die list to pop up. To narrow down the choices we are selecting a V-width of 0.157.

--- A new tooling list appears--- again, you can scroll in to view the part closer. Finally, verify your tooling changes by opening the program screen.

HOW TO ADJUST LOCK THE IMPORTANT SIZE

CAL lock the dimension



http://www.youtube.com/watch?v=jy4IOPpAm0A&feature=related

<Manual cal adj>

This CAL video shows how to lock in a measurement on a blank. .04

While you are on the size page, input the actual blank length by clicking the LENGTH box.

---This is important if the actual blank length was cut based off a different bend deduction.

If you have an area that must be to exact measurement ...CAL allows you to lock-in those lengths , redistributing the bend error to the unlocked line.


Click the ADJ icon. (SAY SLOWLY) **Then click on the lock icon of the line that must be exact.** Notice how the line turns green and that CAL redistributes the error difference to all of the unlocked lines.

Cal is the only program that gives you the ability to lock specific measurements- --We believe that this is one of the best features of CAL.

HOW TO REVERSE TOOLING AND BACK-GAUGE

CAL tool reverse

http://www.youtube.com/watch?v=gFqp4lGOHul



This Cal video will show you how to reverse the punch, die and Back gauge position

Click on your PUNCH for your punch list to appear.

Press the reverse button located at the top of the list.

You can scroll in to view your changes.

Click on your DIE for the die list to appear.

You can press the reverse button located at the top of the list.

Scroll in to view your changes.

The arrow will indicate the material's top side.

CLK the reverse button on the lower R.S. to change the BG position.


Notice that the Back gauge has moved and the material also has changed position.

HOW TO IMPORT CUSTOM DIE

CAL custom die

Manual 01 cal custom die

http://www.youtube.com/watch?v=Y3llVBbah3A



This Cal video will show you how to add a custom die into your inventory.

Clk on the manager icon----Then tools---Choose the custom Die tab & CLK the profile Load button To import the .dxf or .txt file of the Die profile information, shown on the screen. The profile will appear.

The ATTACH POINT: these X and Y measurements are obtained by physically measuring the die. Notice that the die is set to low in the current diagram. However when you enter the correct Y measurement it will correctly show the die position.


Fill in your confirmation information using the reference picture on the upper right side. The WIDTH: 0.5" Your WORK HEIGHT: is the measurement from the neck to the bottom = 2"

HOW TO IMPORT CUSTOM PUNCH

CAL custom punch

Manual 01 cal custom punch

http://www.youtube.com/watch?v=j6Q5D3R1gFE



This Cal video will show you how to add a custom punch into your inventory.

Click on manager icon----& then Tools---Check your custom Punches tab and then the profile LOAD

BUTTON

Import the .dxf or .txt file of the punch profile as shown on the screen. The profile will appear.

Fill in the confirmation information using the reference picture on the upper right side.

We will use Test1 for the Name The STYLE of this punch is European WIDTH: 0.5"

Your WORK HEIGHT is the measurement from the neck to the bottom, which is 3" TONNAGE: 30

We will type in TEST 1 for the MANUFACTURE The TYPE of this punch is Acute Angle

The TIP ANGLE is 30°& the TIP RADIUS is 0.0078


Now Click the Profile +ADD button

Your new custom punch is added to the inventory box on the left side of your screen. Also note that this will reflect back to your total PUNCH inventory

HOW TO SELECT TOOLS MANUALLY

CAL choose tooling manually

http://www.youtube.com/watch?v=xm0jJ7sQrD0



This CAL video will show you how to manually select your tools.

Click the space where the punch would be for the punch list to appear

Choose the specific bracketed tool # for the correct info.

---Then click the play button to complete the bend sequence.


---CAL automatically chooses the die. You can also click on the die to change it.

Scroll in to view your changes.

HOW TO VERIFY THE COLLISION MANUALLY

CAL manual bend sequence





This Cal Video shows you how to correct a manual sequence collision.

When you are using manual sequencing and the number flashes orange –it is warning you of a future bend collision.

--to force the bend, clk on the #. This will stop the flashing and allow you to choose the next bend in the sequence.

Notice that this #3 bend flashes red and shows a collision.

---You can choose a different bend area for bend 3 to work. However, a future collision still remains as shown by #4 flashing red.

To fix this problem clear the sequencing back to the first bend, then choose a different bend sequence. ---Now #3 flashes a warning.

Click the undo button to the #2 bend, choose a different bend for the 3rd and 4th bend to complete.

HOW TO CREATE MULTIPLE PROFILES

CAL multiple profiles

http://www.youtube.com/watch?v=TGcZI8LLIf4

MANAGER · SKETCH SIZE INSERTION ADJUST SEQUENCE PROGRAM SIMULATE OF	
	😔 📵 🚭 🍖 16:43

Manual 01 Cal multiple profile

This Cal video explains how to create multiple profiles for parts, like box enclosures.

Start by making your first profile and then click on the profile bar located on the left side of the screen.

Click the new profile icon and create the second profile side of your part.

Once you have finished the multiple profiles you will complete the regular process of sizing, adjusting and sequencing the 1st profile.

--When that is complete, click on profile 2 to repeat.

The bend sequence page will continue to show each profile separately.

However, the program page will show the total combined bends of both profiles in order. The simulation page also shows your profiles in succession.

HOW TO USE CALICULATOR FOR DEPTH VALUE AND BACK-GAUGE L VALUE

CAL DLC

Manual 01 Cal DLC

http://www.youtube.com/watch?v=OAxR0xB4-Mw

CAL CA	I for RG50[Furope	an]														
MA	NAGER -	SKETCH	SIZE	INSE	TION	ADJUST	SEQUENCE	PRO	BRAM	SIMULA		1				
	34		_		_				<u></u>		_	_				
Profiles	_		Profile	Angle	Flange		BD Bend W	BG L			Punch ID		Depth	1° =	M Angle	
les		1	1	90.000	1.556			1.004	0.000	0.000	46202	07300				
	profile 1	2	1	90.000	3.257			2.780	-0.615	1.180	46202 46202	07300 07300				
		3 V 14 V	1	120.000		-0.086		0.203	0.295	0.000	46202	07300				
		*	-	120.000	0.040	-0.000		-1.000	0.235	0.000	40202	07000				
	profile 2															
I.	•															
	new															
I.																
I.																
I.																
I.																
I.																
I.																
I.																
I.																
1																
I																
1																
I.																
		Material	HR	S T	hickness	0.060	BG Comp	0.000								- 📩 🛃 🚥
1		» 🔏 man	ual 01 cal	dlc 00	😼 Inbox - M	licrosoft O	👔 FW: ソフト	Messa	🚺 Manu	al		CAL for RG50	Europ	😿 Bend Ta	able 🔤 CAL 10 HOW TO CR 📓 manual 11 CAL Narr EN	ا6:46 😒 💽 🕻 🖌

This Cal video explains how to use CAL's program page as a Depth Length calculator or DLC

You can use it as a DLC to find the bend deduction, back gauge length and depth value for any angle that you need to find.

As you can see, CAL automatically adds one empty row at the bottom of the table.

To use the DLC function:

- click on the empty angle box- enter 115°
- click on the empty flange box- enter 3"
- click on the empty punch ID box to choose your punch
- Now click the empty punch id box to choose your Die

This will provide you the: depth, value, bend deduction, back gauge length

HOW TO USE ANGLE CORRECTION

CAL bend angle adjust

This CAL video shows you how to adjust your bend angle.

http://www.youtube.com/watch?v=StcLfb_GX9I

VAGER		ETCH	SIZE	INSERTION	ADJUS	T SEQ		PROGR	am si		OK						
	Profile	Angle	Flange	Adjust BD	Bend W	BGL	BG H	Retract	Punch ID	Die ID	Depth	1° =		м	Angle		
1 🔻	1	90.000	1.556	-0.497		1.004	0.000	0.000	46202	07300							
2	1	90.000		-0.423		2.780	-0.615	1.180	46202	07300							
3	1	90.000		-0.086		0.203	0.295	0.000	46202	07300							
4	2	120.000	0.343	-0.086		-1.000	0.295	0.000	46202	07300							
+		_	_								_	_					

CAL predicts the depth value from the sample data that you created in Bend Table.

If the angle result needs to be adjusted---open the program page to enter your actual material's measured angle into the measured angle box located on the far right side of the table.


We will input 87° click enter.

Notice that the resulting depth changes from .109 to .112.

HOW TO USE MULTIPLE PUNCHES

CAL multiple punch operation

http://www.youtube.com/watch?v=8v-J0xUQoes



Cal multi-punch

This CAL video shows you how to choose multiple punches in the bending sequence.

Manually select the 1st bends in your sequence by clicking the corner bend-----then press the stop button to finish using that tool. The numbers will turn gray.

- Select the next bend, by clicking the corner of the bend and clk the punch to bring up your punch list.
- Select the specific bracketed # of the tool for proper information & complete the manual sequencing.
- Finally--- to set your tooling change press the stop button again. Notice that all of the numbers are gray.

To view the tooling change sequenceyou can click on the left side for the 1st bends and the right side for any of your later bends.

HOW TO ADD A BEND IN PROGRAM

CAL program page

Manual 01 Cal adding a bend in program

http://www.youtube.com/watch?v=JjGo9mOajNA

ANAGER -			1				6	_						
AGER -	SKETCH	SIZE		RTION	ADJUST	SEQUENCE	PROC	RAM	SIMULA	re 💊				
		Profile	Angle	Flange	Adjust E	5D Bend W	BG L	BG H	Retract	Punch ID	Die ID	Depth	1° =	M Angle
	1	1	90.000	17.503			14.577	0.000	0.000	46202	07300			
profile 1	2		90.000		-0.303		0.855	0.615	0.000	46202	07300			
	3		90.000		-0.314		0.889	0.615	0.000	46202	07300			
L	4 5		120.000 90.000		-0.086		-1.000	0.295	0.000	46202 01602	07300 07300			
profile 2	6		90.000		0.000		4.047	0.000	0.000	01602	07300			
	▶7				0.000		-1.000	0.000	0.000	01602	07300			
	*		+											
new		+												
			0											
	Materia	si H	RS	hickness	0.060	BG Comp	0.000							

This Cal video explains how to use CAL's program page to add a bend to your part.

Click the blue triangle where you want to add a row of new bend information.

& Click the plus button to insert the row

- Click on the empty angle box- enter your angle °
- Click on the empty flange box- enter your flange size
- Choose your punch by clicking on the empty punch ID box
- Choose your die by clicking on the empty die ID box

This will provide you with the bend deduction---back gauge length & depth value.

You can adjust the bending sequence by clicking on the blue triangle button of the bend that you want to move and clicking on the down arrow. Also, you can use the up arrow to move it up. Or delete a bend by choosing the red delete button.PLEASE NOTE THAT This Depth Length calculator function was added for your convenience. ---All changes created on the program page do not reflect back to your originally drawn parts. ----

HOW TO USE BACK-GAUGE COMPENSATION

CAL back gauge compensation

		SKETCH	SIZE	NSERTION	ADJUST	SEQUENCE	PROGRAM	SINULATE	OK				
Profiles	3/6									46202			
							Options General	Colors Machin	ne BG Co	omp About	×		
									L valu	Backgauge		╏	
		•											
							Toolin Die	g	asured va	asured value: 0.000			
								Back Room Back	nsation	L value: 0.000 BG Comp: <mark>0.000</mark>		Ĭ	
	•								ок				
								\bigotimes	U	07300			
6	Material I		Thickness			Length 14.780		94 Width		✓ 0.39"/10.0mn	Bend Table	역 CAL 14 HOW T 역 manual 2 Narra EN	< 💽 🔽 (Å. 4)) 17:19

http://www.youtube.com/watch?v=6Sm7XBSRRwA

This CAL video will show you how to verify the back gauge compensation for your machine and tooling

Click the manager icon -> options -> BG comp tab.

- Make sure that the die ID is the same as the one you are using.
- Measured value is physically measured on the shop floor
- Your L value is the readout from your machine's display.

Click the apply BG comp button to reflect this information on your program icon page.

Click OK

Finally, Click program icon to verify the Back Gauge compensation was updated or to review your information.

HOW TO USE INSERTION



Click type to choose pull down menu from library Click code from pull down menu Enter the distance from start or end Enter number of fasteners Enter the space between fasteners

You can select

"start" or "end" for the distance

"in" or "out" for distance is from inside of material or outside of material

"edge" or "center" (default is center)

"in" or "out" for fastener height is inside of material or outside of material (clinching nut is IN)

Custom or special fasteners can be inserted by entering the height and width.

Contact information

Products of Orbit Technology Corporation <u>www.otc.net</u> 2212 Dupont Dr. Suite L Irvine, CA 92612 U.S.A.

Exclusive distributer La Boschiny, Inc. (LBI) 1889 Petaluma Dr. Chula Vista, CA 91913 U.S.A. KATSUMI (GEORGE) KAMIMURA 619-770-8711 kamimura@caleasytouch.com www.caleasytouch.com